

Fire Water Tank Valve

General Industry **ARC 5ES & ARC 5 Coatings** Case Study 137

Challenge

Issue

Cracked and leaking valve required replacement. To repair a draining tank would require taking plant off-line

Goals

- Avoid plant shutdown and repair valve in place
- Await annual shutdown for complete replacement

Root Cause

Aging

Solution

Preparation

- Temporary leak stops were installed
- External of valve was mechanical roughened to SP11 (white metal)

Application

- ARC 5ES was pressed into crack over temporary leak stops
- Two alternating layers ARC 5 and reinforcing mesh was spread over crack

Results

Client Reported

- Repairs carried out in 3 hours without taking tank out of service
- Tank stayed in service without leakage for 6 months, until annual shutdown allowed valve replacement

Savings	\$ 123.800
ARC repair	\$ 1,200
1 day plant shutdown	\$ 125,000

\$=USD



Valve leakage plugged



Reinforcing mesh being placed



Repaired valve

07/14