Secondary Containment

Mining/Mineral & Ore Processing — Refining ARC 797 and 988 Coatings Case Study 065

Challenge

Issue

Regular spills of acid damaged existing coating and underlying concrete after 1 year. Safety risk in traffic areas, and associated environmental fines, were also present.

Goals

- Protect concrete infrastructure against regular leaks from acid leach tanks
- Minimize safety risk and environment fines

Root Cause

30% H₂SO₄ attacks cement in concrete, damaging sumps, tank pads, and pump bases.



Pre-existing condition of concrete

Solution

Preparation

- Pressure wash and decontaminate concrete
- Mechanically roughen to CSP3 finish

Application

- 1. All surfaces primed with ARC 797
- 2. Pitch to grade and top coat with a .25" (6,4 mm) of ARC 988 system

Initial application completed in 2002

Results

Client Reported:

- Achieved goal of protecting concrete from acid leaks
- Safety risks from damaged concrete addressed
- ARC coated and lined surfaces are damage free for over 8 years
- Client continues to use ARC 988 as preferred lining system for concrete protection in all plant areas exposed to acid



ARC coated surfaces with minimal repairs indicated in 2010

EN23593.64

09/14

A.W. Chesterton Company

860 Salem Street, Groveland, MA 01834 USA